


 [Print this page](#)

## SEARCH RESULTS

VIN: 2CXXXXXXXXXXXXXXXXXX

Year: 2012

Vehicle: LANCIA THEMA FOUR DOOR SEDAN

### Questions




Please contact the FCA LLC US Recall Assistance Center at 1-800-853-1403

### Do you Qualify for Recall Reimbursement?

If you've had a recall on your vehicle and have incurred recall-related costs you'll need to start the reimbursement request process (all on a case-by-case basis).

Results Last Updated: August 11, 2016

### Safety Recalls (What is a Safety Recall? [Learn More](#))

Status	FCA Recall #	NHTSA Recall #	Recall Date	Safety Defect/Non Compliance Description and Safety Risk	Repair Description	Recall Status	Reimbursement
 <b>Incomplete</b>	<a href="#">S43</a>	16V-352	May 24, 2016	THE FRONT PASSENGER AIRBAG INFLATOR HOUSING MAY RUPTURE WHILE DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY AND/OR HEAT AGING. IN THE EVENT OF A FRONT PASSENGER AIRBAG INFLATOR RUPTURE, METAL FRAGMENT(S) COULD PASS THROUGH THE AIRBAG CUSHION MATERIAL, WHICH MAY RESULT IN ADDITIONAL INJURY OR DEATH TO VEHICLE OCCUPANTS.	THE PASSENGER AIRBAG INFLATOR MUST BE REPLACED.	<b>INCOMPLETE</b>	<a href="#">SUBMIT REIMBURSEMENT</a>
 <b>Complete</b>	<a href="#">M10</a>	12V-197	May 07, 2012	THE POWER DISTRIBUTION CENTER (PDC) BUS BAR MAY OVERHEAT. THIS COULD CAUSE A LOSS OF ANTILOCK BRAKE SYSTEM (ABS) AND/OR ELECTRONIC STABILITY CONTROL (ESC). A LOSS OF ABS/ESC UNDER CERTAIN DRIVING CONDITIONS COULD CAUSE A CRASH WITHOUT WARNING.	THE ABS/ESC FUSE TYPE MUST BE INSPECTED. VEHICLES THAT DO NOT PASS INSPECTION MUST HAVE THE ABS/ESC FUSE RELOCATED AND THE FUSE TYPE UPGRADED	REPAIRED	<a href="#">SUBMIT REIMBURSEMENT</a>
 <b>Complete</b>	<a href="#">N07</a>	13V-118	April 03, 2013	THE FRONT SEAT AIRBAG WIRING ELECTRICAL CONNECTORS MAY HAVE AN INTERMITTENT ELECTRICAL CONNECTION. IF AN INTERMITTENT ELECTRICAL CONNECTION EXISTS DURING A SIDE IMPACT THE FRONT SEAT AIRBAG LOCATED AT THE OUTBOARD SIDE OF SEATBACK MAY NOT DEPLOY AS INTENDED. THIS COULD CAUSE ADDITIONAL	THE FRONT SEAT AIRBAG WIRE HARNESS FOR BOTH FRONT SEATS MUST BE INSPECTED AND REPLACED IF NECESSARY.	REPAIRED	<a href="#">SUBMIT REIMBURSEMENT</a>

				INJURY TO FRONT SEAT OCCUPANTS DURING A SIDE IMPACT COLLISION.			
--	--	--	--	--	--	--	--

### Viewing 3 of 3 total safety recalls

#### Emissions Recall (What is an Emissions Recall? [Learn More](#))

There are no outstanding emission recalls for the above listed VIN

#### Campaigns (What is a Campaign? [Learn More](#))

Status	Campaign Date	Campaign Description	Repair Description	Comments	Reimbursement
<input type="checkbox"/> Incomplete	October 07, 2013	REPROGRAM NAVIGATION SYSTEM		INCOMPLETE BUT REPAIR PARTS ARE AVAILABLE	<a href="#">SUBMIT REIMBURSEMENT</a>

### Viewing 1 of 1 total campaigns

#### Disclaimer

Notification letters issued prior to 1999 are not available online. Please contact us by email to request a copy.

#### Note

Acrobat Reader 5.0 or later is required to view documents.

[Click here for a free download](#)



[Home](#) | [Fiat Chrysler Automobiles \(FCA\)](#) | [Contact Us](#) | [ChryslerGroup360](#) | [Site Map](#) | [Privacy Policy](#) | [Copyright](#)

©2015 FCA US LLC. All Rights Reserved.

Chrysler, Dodge, Jeep, Ram, Mopar and SRT are registered trademarks of FCA US LLC.

ALFA ROMEO and FIAT are registered trademarks of FCA Group Marketing S.p.A., used with permission.